

Notification of Discontinuation of Part 343-4307

To: All Distributors of STEMCO Wheel End Products

Effective immediately, STEMCO will be discontinuing part number 343-4307 (TireMaxx Hubcap).



Thank you for your continued support of STEMCO.